

SSO Inventory

Town of Burlington, Massachusetts

Revision Date: August 17, 2022

SSO Location ¹	Discharge Statement ²	Date ³	Time Start ³	Time End ³	Estimated Volume ⁴	Description ⁵	Mitigation Completed ⁶	Mitigation Planned ⁷
Junction Bedford St. and Middlesex Turnpike	Discharge entered Vine Brook	4/15/21	3pm	11pm		Discharge from sanitary sewer manhole due to pipe collapse	Bypassed blockage by pumping to next manhole. Dug up broken pipe.	
Junction Middlesex Turnpike and Third Ave	Discharge froze and remained on surface	1/22/22	8pm	9pm	1,000 gallons	Discharge caused by grease blockage	Rodded sewer main 300 feet, cleared blockage and salted road	

¹ Location (approximate street crossing/address and receiving water, if any)

² A clear statement of whether the discharge entered a surface water directly or entered the MS4

³ Date(s) and time(s) of each known SSO occurrence (i.e., beginning and end of any known discharge)

⁴ Estimated volume(s) of the occurrence

⁵ Description of the occurrence indicating known or suspected cause(s)

⁶ Mitigation and corrective measures completed with dates implemented

⁷ Mitigation and corrective measures planned with implementation schedules